

2.13 - Democracy Suite[®] System Change Notes

Version: 5.13-CO::5

April 16, 2021

Table of Contents

Chapter 1: Introduction	1
Chapter 2: Product Changes	2
2.1 EMS Product Changes	2
2.2 ICC Product Changes	4
2.3 ICX BMD Product Changes	5
Revision History	8
List of Tables	9

CHAPTER 1: INTRODUCTION

The Democracy Suite[®] 5.13 voting system is a modification to the certified Democracy Suite[®] 5.11 voting system. The purpose of this modification is to provide the changes described in “Product Changes” on page 2.

CHAPTER 2: PRODUCT CHANGES

The Following tables list the Democracy Suite® 5.13 product changes and reference, where applicable, the documentation revisions detailing the changes.

The products listed are

- EMS, Table 2-1
- ICC, Table 2-2
- ICX BMD, Table 2-3

2.1 EMS Product Changes

Item #	Change Description	Document Title and Section
1.	EED: Added ability to store tabulator resources in the NAS project folder	N/A
2.	RTR: Removed the Byte Order Marker (BOM) from the beginning of the export file	N/A
3.	ADJ: Allow the Adjudicator to complete ballot without resolving Write-In from Contest that is not selected for Adjudication	N/A
4.	ADJ: Changed warning message to be clearer when Adjudicator tries to adjudicate a contest that cannot be adjudicated	N/A

Table 2-1: EMS Product Changes

Item #	Change Description	Document Title and Section
5.	RTR: Added ability to prevent user from overwriting existing images when loading images from the Results folder	<i>Democracy Suite[®] EMS Results Tally & Reporting User Guide, Section 6.4 Loading Results From Directory</i>
6.	RTR: When ballot images are loaded during 'Automatic Results Loading', ensure 'Images Loaded' checkbox is selected and counter is incremented	<i>Democracy Suite[®] EMS Results Tally & Reporting User Guide, Section 6.5 Automatic Result Loading</i>
7.	ADJ: Added Rejection Reasons that allows administrators to customize the set of reasons that adjudicators can choose from when rejecting write-in candidates on a ballot.	<i>ImageCast[®] Adjudication User Guide, Section 2.7 Rejection Reasons</i>

Table 2-1: EMS Product Changes (Continued)

2.2 ICC Product Changes

Item #	Change Description	Document Title and Section
1.	Modified ICC log entry text to be more descriptive for double feed errors	N/A
2.	Corrected functionality to allow discarding of batches after 999	N/A
3.	Modified ICC to not accept a batch without a Poll ID	N/A
4.	Added ability to print Batch Header Cards from ICC	N/A
5.	Added support for HiPro firmware 1.0.1074	<i>Democracy Suite® ImageCast® Central Installation and Configuration Procedures, Section 2.2 Software Environment</i>
6.	Changed maximum Poll ID length from 6 characters to 32	N/A

Table 2-2: ICC Product Changes

2.3 ICX BMD Product Changes

Item #	Change Description	Document Title and Section
1.	Added support for ICX BMD to produce a ballot without a barcode	<p><i>2.02 - Democracy Suite® System Overview, Section 2.7.1.1 Uniform Ballot</i></p> <p><i>2.03 - Democracy Suite® ImageCast® X System Functionality Description 2.2.1 BMD - Ballot Marking Device Mode</i></p> <p><i>2.03 - Democracy Suite® EMS Functionality Description 3.4.6.6 The Democracy Suite® EMS Election Domain Model</i></p> <p><i>Democracy Suite® ImageCast® X User Guide Appendix D Configuring the ICX for Printing Human Readable Ballots</i></p>
2.	Added support for Avison AP3061 printer	<p><i>2.02 - Democracy Suite® System Overview, Section 3.6.1 Hardware Configuration</i></p> <p><i>2.08 - Democracy Suite® ImageCast® X System Operations Procedures, Section 2.1 System Interface</i></p> <p><i>Democracy Suite® ImageCast® X System Installation and Configuration, Section 7.6 Avison AP3061 Configuration</i></p>

Item #	Change Description	Document Title and Section
3.	Added option to display only a 10-key keyboard when only numeric values are required for entry	<i>Democracy Suite[®] ImageCast[®] X Machine Configuration File (MCF) Parameters Settings, Table 2-2 Admin Options</i>
4.	Added option to print a Daily Print Report that provides statistics for auditing but no results	<i>Democracy Suite[®] ImageCast[®] X User Guide, Section 3.2.2.4 Print</i>
5.	Added support for new Aegis USB memory devices	N/A
6.	Corrected scroll bar display on Samsung device when first voting session after power up is an accessible voting session	N/A

Table 2-3: ICX BMD Product Changes


REVISION HISTORY

Rev.	Date	Author	Summary
5	04-16-2021	████████	Updated document references in Table 2.3, row 1
4	04-08-2021	████████	Stylistic and formatting updates made.
3	02-26-2021	████████████████	Revised Table 2-1 to add items 3 - 6
2	12-03-2020	████████████████	Added change notes
1	07-29-2020	████████████████	Branched for 5.13-CO

LIST OF TABLES

Table 2-1: EMS Product Changes	2
Table 2-2: ICC Product Changes	4
Table 2-3: ICX BMD Product Changes	7

End of Document



**DOMINION
VOTING**

Our customers come first.

